

Survey Key Findings and Recommendations

1. Suggest homeowners ask the septic pumper what type of septic tank they have.
" Recommend precast, fiberglass or plastic.
2. If septic system is older than 30 years, committee recommends replacement.
3. Committee is concerned about homeowners who never had septic tanks pumped.
4. With the new septic bylaw, the pumper will visually inspect the septic system at time of pumping.
5. Committee recommends a septic tank riser for ease of location and maintenance.
6. If a septic filter is installed,, it is important to clean every six months.
7. Committee notes the majority of homeowners are willing to share their water test results with the municipality.
8. Most homeowners had no problems with their drinking water.
9. Homeowners are encouraged to check their well cap seals.
10. Committee recommends that Council share the survey results on the community website.